

KANDIYOHI COUNTY (34)

Number of lakes 361
 Lake area, acres. 61,637

Kandiyohi County lake basins originate from the uneven deposition of glacial till in ground moraine and from ice block depressions in terminal moraine. Big Kandiyohi, 34-86, is a large shallow lake formed in ground moraine. Such basins often undergo severe fluctuation of water levels. In contrast, Green, 34-79, is a large deep lake, typical of basins formed by ice block depressions in the terminal moraine region which extends through the northern part of the county.

The following table lists some of the large lakes entirely within the county:

Ident. no.	Name	Area, acres
34-79	Green	5,821
34-86	Big Kandiyohi	2,877
34-251	Norway	2,496
34-169	Wagonga	1,792
34-192	Long	1,715
34-44	Diamond	1,697
34-72	Lillian	1,608
34-62	Calhoun	1,396
34-170	Grass	1,227
34-22	Elizabeth	1,153
34-154	Nest	1,019

Mud, 34-158, was formed by reconstructing a former mill dam which had been built on the Middle Fork of the Crow River at New London in 1864. As a result of the dam reconstruction, Mud Lake, a meandered lake, was enlarged to its present area which is nearly eight times as great as the natural basin.

Lakes classified by area

	Area in acres												Total
	10 to 25	25 to 50	50 to 75	75 to 100	100 to 125	125 to 150	150 to 200	200 to 500	500 to 1000	1000 to 2500	2500 to 5000	5000 and more	
Number listed	71	93	60	34	20	15	14	28	14	9	2	1	361
Number affected by drainage or dry	22	50	39	17	12	5	6	11	3	1	1	0	167

Ident. number	Name	Range	Township	Location Section	Area in Acres	Meandered	Remarks
47-207					3 (188)	...	See Meeker County (47).
47-208					5 (19)	...	Do.
34-1		33	117	4,5	126	x	Affected by J.D. 1.
34-2	Emma	33	117	4,9	180	x	Do.
34-3	Dog	33	117	8,9,16,17	538	x	Do.
34-4		33	117	11,14	110	x	Affected by C.D. 52.
34-5		33	117,118	1,2,35,36	141	x	
34-6		33	118	SE 1,12	32	...	Affected by ditch.
34-7		33	118	SW 1,12	53	...	Do.
34-8		33	118	2,11	67	...	Do.

MINNESOTA CONSERVATION DEPARTMENT

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
34-9		33	118	3,10	35	...	
34-10		33	118	5	38	...	Affected by ditch.
34-11		33	118	10	43	...	
34-12	Johnson	33	118	10,11	115	x	
34-13	Otter	33	118	10,15	79	x	
34-14		33	118	WC 12	35	...	Affected by ditch.
34-15		33	118	EC 12	24	...	Do.
34-16		33	118	14,15,23	49	...	Do.
34-17		33	118	15	47	...	Do.
34-18		33	118	27	43	...	Do.
34-19		33	118	32	67	...	
34-20		33	118	34	73	...	Affected by J.D. 1.
34-21	Mud	33	118,119	1,2;35,36	69	x	
34-22	Elizabeth	33	118,119	2,3,4;34,35	1,153	x	
34-23	Pay	33	119	2	51	x	
34-24		33	119	5	55	...	
34-25		33	119	7	12	...	
34-26		33	119	8	123	...	
34-27	Summit	33	119	9,10,15,16	151	x	
34-28		33	119	11	22	...	
34-29		33	119	15	16	...	
34-30		33	119	17	27	...	Affected by ditch.
34-31		33	119	22	25	...	
34-32	Carrie	33	119	26,35	93	x	
34-33	Ella	33	119	27,28,33,34	153	x	
34-34		33	120	1,2	41	...	Affected by C.D. 28.
34-35		33	120	2	65	...	Do.
34-36		33	120	6,7	20	...	Do.
34-37		33	120	7,8	57	...	Do.
34-38		33	120	7,18	48	...	Do.
34-39		33	120	8,9,16,17	23	...	Do.
34-40	Sperry	33	120	9,15,16	153	x	Do.
34-41		33	120	14	33	...	Do.
34-42	Rieff	33	120	14,15	33	...	Do.
34-43	Swenson	33	120	15	83	x	Do.
34-44	Diamond	33	120	16,19-21,28-30	1,697	x	Dam at outlet.
34-45		33	120	17	29	...	Affected by C.D. 28.
34-46	Taits	33	120	18,19	99	x	
34-47	Thomas	33	120	21,22	116	x	
34-48		33	120	23	19	...	Affected by ditch.
34-49	Schultz	33	120	23,26	188	x	
34-50		33	120	24	28	...	Affected by ditch.
34-51	Wheeler	33	120	26,27,34,35	324	x	
34-52		33	120	27	13	...	
34-53		33	120	27,28	25	...	Affected by ditch.
34-54	Hubbard	33	120	27,28,33,34	44	...	
34-55		33	120	29,31,32	33	...	
34-56		33	120	29,32	52	x	
34-57		33	120	30	35	...	Affected by ditch.
34-58		33	120	33	32	...	Affected by C.D. 45.
34-59		33	120,121	4;33	40	...	Affected by C.D. 9.
34-60	Jesse	33	120,121	6;31	87	x	
34-61	Shoemaker	33	121	6,7	53	...	
34-62	Calhoun	33	121	16,20-22,27,28	1,396	x	Dam at outlet.
34-63		33	121	23	20	...	Affected by ditch.
34-64	Middle	33	121	27	112	...	Affected by C.D. 20.
34-65		33	121,122	4;33	42	...	
34-66	Long	33	121,122	5,6;31,32	356	x	Dam at outlet.
34-67		33	122	1	47	...	
34-68	Reamer	33	122	22	29	...	

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
34-69		33	122	27	30	...	
34-70		33	122	30,31	30	...	Affected by ditch.
34-71		33	122	34,35	51	...	Do.
34-72	Lillian	33,34	117	5,6,7;1,11-14	1,608	x	Dam at outlet.
34-73	Cherry	33,34	118	6:1	70	x	
34-74	Charlotte	33,34	118	19,30;24	203	x	
34-75		33,34	118	30;25	52	...	Affected by J.D. 17.
34-76	Minnetaga	33,34	119	29-32;25,36	786	x	
34-77		33,34	120	7,18;12,13	52	...	Affected by ditch.
34-78	Bass	33,34	120	18,19;13	55	x	
34-79	Green	33,34	120,121	various	5,821	x	
65-78	Fox				375 (1,078)	x	See Renville County (65).
34-80		34	117	SW 7	33	...	Affected by Blomkest ditch.
34-81		34	117	9	56	...	Affected by C.D. 24.
34-82		34	117	NW 18	34	...	Affected by C.D. 8.
34-83		34	117	21,28	113	...	Affected by C.D. 24.
34-84		34	117	22	46	...	Do.
34-85		34	117	26	46	...	Do.
34-86	Big Kandiyohi	34	117,118	3,20-23,26-29,31-35	2,877	x	Affected by C.D. 24. Dam at outlet.
34-87		34	118	2,3,10,11	163	...	Affected by J.D. 1.
34-88	Fanny	34	118	8,9,16,17	207	x	Do.
34-89		34	118	14,15,23	31	...	
34-90		34	118	15,16	46	...	Affected by J.D. 1.
34-91		34	118	16,17,21	81	...	Do.
34-92		34	118	18,19	67	...	Affected by C.D. 4.
34-93		34	118	23	61	...	Affected by J.D. 1.
34-94	Mary	34	118	23-26	87	...	Do.
34-95		34	118	26,35	81	...	
34-96	Little Kandiyohi	34	118,119	1-3;33-36	932	x	Dam at outlet.
34-97	Eleanor	34	118,119	6,31,32	251	x	Affected by C.D. 23.
34-98		34	119	NE 1	73	x	Affected by ditch.
34-99		34	119	SC 1	30	...	Do.
34-100		34	119	4	44	...	Affected by C.D. 33.
34-101		34	119	6	30	...	Do.
34-102		34	119	6,7	74	...	Do.
34-103		34	119	10,15	50	...	Affected by C.D. 23.
34-104	Peach	34	119	16,17	109	x	Do.
34-105	Kasota	34	119	25,35,36	469	x	
34-106	Swan	34	119	26,27,34,35	269	x	
34-107		34	119,120	1,2;35,36	79	...	Affected by ditch.
34-108		34	119,120	2;35	73	...	Do.
34-109		34	119,120	2,3;34	57	...	Do.
34-110		34	120	NC 1	23	...	
34-111		34	120	C 1	40	...	
34-112	Woodcock	34	120	1,2,11,12	151	x	
34-113		34	120	3,10	39	...	
34-114	Carlson	34	120	4,9	31	x	
34-115	East Twin	34	120	5-8	160	x	
34-116	Henderson	34	120	6	91	x	
34-117	West Twin	34	120	7	89	x	
34-118		34	120	9	77	...	Affected by ditch.
34-119	Elkhorn	34	120	9,10,15,16	79	x	
34-120	Alvig	34	120	10	88	x	
34-121		34	120	11,14	24	...	
34-122		34	120	12	75	...	
34-123		34	120	13	23	...	
34-124		34	120	13,14,23,24	23	...	
34-125		34	120	14	35	...	
34-126		34	120	14,15	61	x	
34-127		34	120	15,22	10	...	

MINNESOTA CONSERVATION DEPARTMENT

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
34-128		34	120	16	19	...	
34-129		34	120	21	19	...	
34-130		34	120	21,22	19	...	Affected by ditch.
34-131		34	120	22	21	...	
34-132		34	120	24	39	...	
34-133		34	120	25	22	...	Affected by ditch.
34-134		34	120	26	25	...	
34-135		34	120	26,27	17	...	
34-136		34	120	28,33	40	...	Affected by ditch.
34-137		34	120	30	15	...	
34-138		34	120	31	33	...	Affected by C.D. 38.
34-139	Burr Oak	34	120	33	41	x	
34-140		34	120	34	43	...	Affected by ditch.
34-141	Woodcock	34	120,121	4,5;33,34	170	x	
34-142	George	34	120,121	6;31,32	248	x	
34-143		34	121	C 4	27	...	
34-144		34	121	SW 4	13	...	
34-145		34	121	5	23	...	
34-146	Eight	34	121	5,8	89	...	
34-147		34	121	6	23	...	
34-148	Bear	34	121	7	140	x	
34-149		34	121	8	49	...	Affected by ditch.
34-150		34	121	12	27	...	
34-151		34	121	12,13	17	...	
34-152		34	121	14,15	13	...	
34-153	Cedar Island	34	121	17,18	330	x	Affected by ditch.
34-154	Nest	34	121	20-22,27-29,32,33	1,019	x	Dam at outlet.
34-155		34	121	30,31	19	...	
34-156		34	121	C 33	29	...	
34-157		34	121	SC 33	37	...	
34-158	Mud	34	121,122	various	2,516	x	Recreation Reservoir.
34-159		34	122	5,6	101	...	Affected by J.D. 3.
34-160		34	122	10	44	...	
34-161		34	122	11,14	32	...	
34-162		34	122	19,30	67	...	Affected by C.D. 37.
34-163	Twenty	34	122	20	109	x	Do.
34-164		34	122	23,24,25,26	83	...	
34-165		34	122	23,26	57	...	
34-166		34	122	26	124	...	Affected by ditch.
34-167		34	122	32	75	...	Do.
34-168	Grove	34,35	117	18,19;13,24	203	x	Affected by C.D. 8.
34-169	Wagonga	34,35	118,119	4-8;32,33;1,10,11,12	1,792	x	Dam at outlet.
34-170	Grass	34,35	119	19,30;23-26	1,227	x	Affected by C.D. 23.
34-171	Eagle	34,35	120	19,30;24,25	891	x	Dam at outlet.
34-172	Ringo	34,35	120,121	6,7;31;1,2,11,12;36	774	x	
34-173		34,35	121	7,18;13	114	x	Affected by ditch.
34-174		34,35	122	7;12	259	...	Affected by C.D. 37.
34-175	Milton	35	118	7,18	276	x	Affected by C.D. 3 & 31.
34-176		35	118	10,11,14,15	60	...	Affected by C.D. 31.
34-177	Stevens	35	118	19,20,29	83	x	Do.
34-178		35	118	29	27	...	
34-179		35	118	30	39	...	Affected by C.D. 31.
34-180	Wilmar	35	119	1,2,10,11,15	761	x	
34-181	Foot	35	119	9,10,16	576	x	Dam at outlet.
34-182		35	119	4	20	...	
34-183		35	119	6,7	33	...	Affected by ditch.
34-184		35	119	8	47	...	Affected by C.D. 12.
34-185		35	119	30	85	...	Affected by C.D. 46.
34-186	Swan	35	119,120	2;35,36	255	x	
34-187	Rasmus	35	119,120	5;32	123	x	Affected by C.D. 12.

Ident. number	Name	Range	Township	Location Section	Area in Acres	Meandered	Remarks
34-188		35	119,120	6:31,32	78	...	Do.
34-189		35	120	NC 4	23	...	
34-190		35	120	WC 4	13	...	Affected by ditch.
34-191		35	120	5,8	35	...	Do.
34-192	Long	35	120	11-15,22,23	1,715	x	
34-193	Point	35	120	13,23,24	157	x	
34-194		35	120	20	55	...	
34-195	King	35	120	22,23,26,27	127	x	
34-196	Skataas	35	120	26,35	218	x	
34-197		35	120	27	25	...	Affected by ditch.
34-198		35	120	28	30	...	
34-199		35	120	28,33	101	...	Affected by ditch.
34-200		35	120	NE 33	11	...	
34-201		35	120	33,34	20	...	
34-202		35	120	34	17	...	Affected by ditch.
34-203	Ringo	35	120,121	1:36	41	x	
34-204	Florida Slough	35	120,121	3,4,9,10:33,34	772	x	Dam at outlet.
34-205		35	120,121	5:32,33	93	...	Affected by ditch.
34-206	Andrew	35	121	2,3,10-12	781	x	
34-207	Henchien	35	121	3	63	...	
34-208	Middle	35	121	3,4,9,10	440	x	
34-209		35	121	14	13	...	
34-210		35	121	15	20	...	Affected by ditch.
34-211		35	121	SE 17	33	...	Do.
34-212		35	121	NW 17	16	...	
34-213		35	121	18	99	...	Affected by ditch.
34-214		35	121	21	51	...	Do.
34-215		35	121	21,22	99	...	Do.
34-216	Norstedt	35	121	23-26	140	x	
34-217	Florida	35	121	26,27,34,35	801	x	Dam at outlet.
34-218	Crook	35	121	28,29,31,32	367	x	
34-219		35	121	30	31	...	Affected by ditch.
34-220		35	121	34,35	81	x	
34-221		35	121	36	47	...	
34-222		35	121,122	2:35	33	...	
34-223	Swan	35	121,122	3,4:33,34	311	x	Dam at outlet.
34-224	Games	35	121,122	4,5:30-33	557	x	Do.
34-225	Fish	35	122	3,4,9,10	389	x	Affected by J.D. 3.
34-226		35	122	7,8	129	...	
34-227	Hystad	35	122	7,18	127	...	
34-228		35	122	8	21	...	
34-229	Thompson	35	122	9,10	103	x	
34-230		35	122	SW 10	61	...	Affected by C.D. 37.
34-231		35	122	NC 10	40	...	Do.
34-232		35	122	13	64	...	Do.
34-233		35	122	13,14,23,24	57	...	Do.
34-234	Prairie	35	122	14,22,23,26	326	x	Do.
34-235		35	122	17	23	...	
34-236		35	122	17-20	135	...	
34-237		35	122	18	24	...	
34-238		35	122	20	27	...	
34-239		35	122	20,29	47	...	
34-240	Timber	35	122	21,22	308	x	Affected by C.D. 37.
34-241		35	122	21,28	13	x	Do.
34-242	Stauffers	35	122	24,25	130	x	Do.
34-243	Skull	35	122	27,28	57	x	Affected by C.D. 37.
34-244		35,36	119	31,36	29	...	Affected by C.D. 47.
34-245	West Solomon	35,36	120	19,30:24,25	560	x	
34-246	East Solomon	35,36	120	20,21,28-30:25	733	x	
34-247		35,36	120	30,31:25,36	57	x	Affected by ditch.

MINNESOTA CONSERVATION DEPARTMENT

Ident. number	Name	Range	Township	Location Section	Area in Acres	Meandered	Remarks
34-248		35,36	121	7,12	31	...	Affected by C.D. 27.
34-249	Mary	35,36	121	18,19,13,24	109	x	
34-250		35,36	121	30,25	16	...	Affected by ditch.
34-251	Norway	35,36	121,122	various	2,496	x	Dam at outlet.
34-252		35,36	122	18,13	67	...	Affected by ditch.
34-253		35,36	122	19,24	30	...	
34-254		36	117,118	3,34	51	...	Affected by J.D. 3.
34-255		36	117,118	4,33	69	...	Do.
34-256		36	118	1	51	...	Affected by C.D. 49.
34-257		36	118	1,12	93	...	Affected by C.D. 31.
34-258		36	118	5	38	...	Affected by J.D. 1.
34-259		36	118	NE 6	31	...	Do.
34-260		36	118	NW 6	25	...	Do.
34-261		36	118	SW 6	48	...	Do.
34-262		36	118	11	85	...	Affected by C.D. 10.
34-263		36	118	12,13	55	...	Affected by C.D. 31.
34-264		36	118	14	42	...	Affected by C.D. 10.
34-265		36	118	22,27	75	...	Affected by C.D. 31.
34-266	Olson	36	118	26,27	130	x	Do.
34-267		36	118	27	63	...	
34-268	Vicks	36	118	28,33	94	x	Affected by J.D. 3.
34-269		36	118	34	103	x	Do.
34-270		36	119	1	34	...	Affected by C.D. 7.
34-271		36	119	1,2	17	...	Do.
34-272		36	119	6	75	...	Do.
34-273		36	119	7,8	44	...	Affected by C.D. 7.
34-274		36	119	10	50	...	Do.
34-275		36	119	17,18	65	...	Affected by J.D. 6.
34-276		36	119	19,30	39	...	Do.
34-277		36	119	21	53	...	Do.
34-278		36	119	26,27	190	x	Affected by C.D. 10.
34-279		36	119	29	24	...	Affected by J.D. 6.
34-280		36	119	32	35	...	
34-281		36	119	33,34	123	x	Affected by J.D. 6.
34-282		36	119	34,35	23	...	Affected by C.D. 10.
34-283	Saint Johns	36	119,120	1,2,35,36	240	x	
34-284		36	120	5,8	20	...	
34-285	Swan	36	120	9,10,15,16	276	x	Affected by ditch.
34-286		36	120	10	23	...	Do.
34-287	Mamre	36	120	11,12,14	266	x	
34-288	Bunning	36	120	14	30	x	
34-289		36	120	19	56	...	Affected by ditch.
34-290		36	120	20,29	40	...	
34-291		36	120	21	16	...	
34-292	Church	36	120	22,23	63	x	
34-293		36	120	22,27	23	...	
34-294	Lindgren	36	120	25,26	75	x	
34-295		36	120	SE 26	12	...	
34-296		36	120	SC 26	19	...	
34-297	West Lindgren	36	120	NW 26	70	x	
34-298		36	120	EC 28	27	...	Affected by C.D. 17.
34-299		36	120	WC 28	21	...	
34-300		36	120	34	33	...	
34-301		36	120	35	17	...	Affected by ditch.
34-302		36	120	35,36	13	...	
34-303		36	120	36	53	...	Affected by C.D.
34-304		36	120,121	5,32	61	...	Affected by ditch.
34-305		36	121	2	20	...	
34-306	Knutsons	36	121	3	67	...	
34-307		36	121	3,4,9,10	137	x	

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
34-308		36	121	6	23	...	
34-309		36	121	7,8	191	x	Affected by C.D. 27.
34-310	West	36	121	8,9,16,17	142	x	Do.
34-311		36	121	9,10,15,16	539	x	Do.
34-312		36	121	14,23	108	x	Do.
34-313	Sand	36	121	16,17,20,21	141	x	Do.
34-314		36	121	17,18	49	...	Do.
34-315		36	121	19,20	58	...	Do.
34-316	Henjum	36	121	21-23,27,28	230	x	
34-317		36	121	21,28	20	...	
34-318		36	121	WC 22	22	...	
34-319		36	121	NC 22	18	...	
34-320		36	121	24	67	...	Affected by ditch.
34-321	Swenson	36	121	24,25	123	x	
34-322		36	121	25	57	...	Affected by ditch.
34-323		36	121	25,36	43	...	
34-324		36	121	27,28,33	37	...	
34-325		36	121	NE 28	21	...	
34-326		36	121	SE 28	23	...	
34-327		36	121	NW 28	36	...	
34-328		36	121	EC 30	19	...	
34-329		36	121	NW 30	21	...	Affected by ditch.
34-330		36	121	31	17	...	
34-331		36	121	31,32	19	...	Affected by ditch.
34-332		36	121	32	17	...	
34-333		36	121	35	18	...	Affected by ditch.
34-334		36	121,122	3,34	56	...	
34-335		36	121,122	4,33	58	...	
34-336	East Sunburg	36	121,122	5,6,31,32	262	...	
34-337		36	122	SE 4	16	...	
34-338		36	122	4,9	27	...	
34-339	Brenner	36	122	5-8	97	x	
34-340		36	122	9,10	27	...	
34-341		36	122	9,16	65	...	
34-342	Ole	36	122	10,11,15	133	x	
34-343		36	122	11,14	30	...	
34-344	Deer	36	122	12	52	...	Affected by ditch.
34-345	Blaamyhre	36	122	15,21,22	121	x	Originally meandered with Glesne Lake as one lake.
34-346		36	122	16,17	192	...	Affected by C.D. 15.
34-347	Hefta	36	122	17,18	140	x	
34-348		36	122	19,30	93	...	
34-349		36	122	20	28	...	
34-350		36	122	20,21,28	192	...	
34-351		36	122	20,29	67	...	
34-352	Glesne	36	122	21,22	205	x	Originally meandered with Blaamyhre Lake as one lake.
34-353		36	122	SW 22,27	70	x	Affected by C.D. 29.
34-354		36	122	SE 22,27	35	...	
34-355		36	122	29	33	...	
34-356		36	122,123	1,36	16 (17)	...	Also in Pope County (61).
34-357	Crook	36	122,123	2,3,35	83 (95)	x	Do.
61-2	East Johanna				8 (123)	x	See Pope County (61).
61-3	Round				3 (36)	...	Do.
61-4					7 (33)	...	Do.
12-1	Bad Water				76 (339)	x	See Chippewa County (12).
34-358	Vick	36,37	118	29,30,31,25	187 (242)	x	Also in Chippewa County (12). Drained by J.D. 3
34-359	Sunburg	36,37	121,122	6,30,31,1,36	329 (416)	...	Also in Swift County
34-360		36,37	122	6:1	15 (20)	...	Do.
34-361		36,37	122	30:25	15 (17)	...	Do.

