

STEVENS COUNTY (75)

Number of lakes 313
 Lake area, acres. 19,394

Many of the basins in the county were formed by the irregular deposition of glacial till. Several chains of lakes were formed by ice blocks deposited in outwash along preglacial valleys. One chain, in Township 126 North, Range 41 West, is located along the Pomme de Terre River Valley. It includes North Pomme de Terre, 75-61, Middle Pomme de Terre, 75-74, and Perkins, 75-75. Another chain in the northeast corner of Township 125 North, Range 42 West, includes North Wintermute, 75-125, Middle Wintermute, 75-105, and South Wintermute, 75-113. Ice blocks deposited in till formed some of the lake basins along the east-central part of the watershed in a morainal region. Round, 75-52, is a typical example.

Nearly half of the lakes listed in the county are affected by artificial drainage and many are dry most of the time.

The largest lakes in the county are: Moose Island, 75-238, 969 acres; Long, 75-24, 588 acres; Gorder, 75-203, 556 acres; and Perkins, 75-75, 519 acres.

Lakes classified by area

	Area in acres									
	10 to 25	25 to 50	50 to 75	75 to 100	100 to 125	125 to 150	150 to 200	200 to 500	500 to 1000	Total
Number listed	126	92	32	16	13	7	10	13	4	313
Number affected by drainage or dry	57	51	16	10	6	4	1	6	1	152

Ident. number	Name	Range	Location		Area in Acres	Meandered	Remarks
			Township	Section			
75-1	40,41	124,125	6;1,31	84 (102)	...	Also in Pope County (61).
61-216	Otter	22 (77)	...	See Pope County (61).
75-2	Cyrus	40,41	125	30;25,36	227 (245)	x	Also in Pope County (61).
75-3	40,41	126	31;36	15 (27)	...	Do.
75-4	41	123	12	62	...	Affected by ditch.
75-5	41	123	18	11
75-6	Durkee	41	123	19,20,29,30	62	x	Affected by J.D. 2.
75-7	41	123,124	2;35	29	...	1951 air photos show part of bed exposed.
75-8	41	123,124	6;31	23	...	Do.
75-9	41	124	3,4	31
75-10	41	124	NE 5	24	...	Affected by C.D. 29.
75-11	41	124	NW 5	22	...	Affected by C.D. 20.
75-12	41	124	8,9	12
75-13	41	124	9	13
75-14	41	124	12	12	...	Affected by ditch.
75-15	41	124	12,13	124
75-16	41	124	15,22	49	...	Affected by C.D. 6.
75-17	41	124	16	17	...	Affected by ditch.
75-18	41	124	22	47	x	Affected by C.D. 6.
75-19	Page	41	124	22,26,27,34	364	x
75-20	41	124	29,32	38	...	Affected by ditch.
75-21	41	124	33,34	13
75-22	41	124	35	23	...	1951 air photos show part of bed exposed.

MINNESOTA CONSERVATION DEPARTMENT

Ident. number	Name	Range	Location		Area in Acres	Meandered	Remarks
			Township	Section			
75-23	41	124	36	32	...	Affected by ditch.
75-24	Long	41	124,125	2,3,10;26,35	588	x	
75-25	North Baker	41	125	3	28	x	
75-26	Baker	41	125	3,10	50	x	
75-27	41	125	7,18	17	...	Affected by ditch.
75-28	41	125	8	30	...	
75-29	Foss	41	125	8,17	50	x	
75-30	41	125	9	18	...	
75-31	41	125	9,10	19	...	Affected by ditch.
75-32	41	125	9,16	10	...	
75-33	41	125	10	13	...	
75-34	Bjork	41	125	10,15	59	x	
75-35	41	125	11	16	...	
75-36	Scandia	41	125	11,14,15	84	x	
75-37	Moore	41	125	13,14,23	193	x	
75-38	41	125	13,24	13	...	
75-39	41	125	15	14	...	
75-40	41	125	15,16	31	...	
75-41	Hanson	41	125	15,22	115	x	
75-42	41	125	19	14	...	
75-43	41	125	NW 20	31	...	
75-44	41	125	NE 20	12	...	
75-45	Hanse	41	125	22,23	107	x	
75-46	Olson	41	125	23-25	348	x	
75-47	41	125	23,26	18	...	Affected by ditch.
75-48	41	125	28	17	...	Affected by C.D. 29.
75-49	41	125	29,32	45	...	Do.
75-50	41	125	C 32	31	...	
75-51	41	125	SE 32	11	...	Affected by C.D. 29.
75-52	Round	41	125	SW 36	62	...	
75-53	41	125	EC 36	18	...	
75-54	41	125,126	E 1:36	23	...	
75-55	41	125,126	W 1:36	27	...	
75-56	Swan	41	125,126	2,3;26,34,35	243	x	
75-57	41	126	2	26	...	
75-58	41	126	3,10	12	...	
75-59	41	126	4	22	...	Affected by ditch.
75-60	41	126	7	27	...	
75-61	North Pomme de Terre	41	126	7,8,17,18	425	x	
75-62	Winters Slough ..	41	126	8,17	48	x	
75-63	41	126	10	28	...	
75-64	Erickson	41	126	10,11	53	x	
75-65	41	126	10,15,16	22	...	
75-66	41	126	11,14	23	...	
75-67	41	126	14	11	...	
75-68	41	126	14,15	19	...	
75-69	41	126	15	11	...	
75-70	41	126	15,16,21,22	27	...	Affected by ditch.
75-71	41	126	15,22,23	52	...	Do.
75-72	41	126	16	37	...	
75-73	41	126	17,20	38	...	
75-74	Middle Pomme de Terre	41	126	18-20	193	x	
75-75	Perkins	41	126	19,20,29,30	519	x	Dam at outlet.
75-76	41	126	20	14	...	Affected by ditch.
75-77	41	126	20,21	44	...	Do.
75-78	41	126	22	17	...	
75-79	41	126	23	12	...	

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
75-80		41	126	25	18	...	
75-81		41	126	27	16	...	
75-82		41	126	NC 29	18	...	
75-83		41	126	WC 29	15	...	
75-84		41	126	33,34	17	...	
75-85		41	126	36	16	...	
75-86		41,42	126	19,24	26	...	Affected by ditch.
75-87		41,42	126	19,30,24,25	23	...	
75-88		41,42	126	30,25	56	...	
75-89		42	123	5,6,8	59	...	Affected by ditch.
75-90		42	123	SW 6	13	...	Do.
75-91		42	123	NW 6	16	...	
75-92		42	123	19	12	...	Affected by ditch.
75-93		42	123	22	13	...	
75-94		42	123	27	27	...	Affected by ditch.
75-95		42	123	35	50	x	
75-96	Crissy	42	124	1,12	97	...	Recreation reservoir.
75-97	Crystal	42	124	3	196	x	
75-98		42	124	3,4,9,10	34	...	Affected by ditch.
75-99	Goulds	42	124	4,5	107	x	Affected by C.D. 16.
75-100	Coleman Slough	42	124	13	16	...	
75-101	Horseshoe	42	124	15,16	60	x	
75-102		42	124	16	20	...	
75-103		42	124	28	18	...	Affected by ditch.
75-104		42	124,125	5,32,33	125	x	Affected by C.D. 16.
75-105	Middle Wintermute	42	125	1,2,12	61	x	Originally meandered with two other lakes as one lake.
75-106		42	125	2	17	...	
75-107		42	125	2,11	59	...	
75-108		42	125	C 3	48	x	Affected by ditch.
75-109		42	125	WC 3	12	...	
75-110		42	125	4,5	29	...	Affected by ditch.
75-111		42	125	7	94	x	Do.
75-112		42	125	9	23	...	Do.
75-113	South Wintermute	42	125	12	174	x	Originally meandered with two other lakes as one lake.
75-114		42	125	12,13	10	...	
75-115		42	125	16	20	...	
75-116	North Maughan	42	125	21,22	86	x	Affected by ditch.
75-117	South Maughan	42	125	21,22,27	173	x	Air photo shows bed exposed.
75-118		42	125	23,24	219	x	Do.
75-119		42	125	24	12	...	Do.
75-120		42	125	26	100	x	Affected by C.D. 12.
75-121		42	125	28	42	...	Affected by C.D. 5.
75-122		42	125	29,30	16	...	Affected by ditch.
75-123		42	125	30	21	...	
75-124		42	125	33	29	...	Affected by C.D. 16.
75-125	North Wintermute	42	125,126	2,35,36	39	x	Originally meandered with two other lakes as one lake.
75-126		42	126	1,12	16	...	Affected by ditch.
75-127		42	126	2	38	...	Do.
75-128		42	126	SE 4	14	...	
75-129		42	126	NW 4	65	...	Affected by ditch.

MINNESOTA CONSERVATION DEPARTMENT

Ident. number	Name	Range	Township	Location Section	Area in Acres	Meandered	Remarks
75-130		42	126	4,5	27	...	Do.
75-131		42	126	5,6	32	...	Do.
75-132		42	126	6	16	...	
75-133		42	126	7	39	...	
75-134		42	126	7,18	21	...	Affected by ditch.
75-135		42	126	C 8	15	...	Do.
75-136		42	126	EC 8	23	...	Do.
75-137		42	126	9	40	...	Do.
75-138		42	126	WC 10	24	...	Do.
75-139		42	126	NE 10	11	...	Do.
75-140		42	126	C 11	91	...	Do.
75-141		42	126	SC 11	19	...	Do.
75-142		42	126	11,12	31	...	Do.
75-143		42	126	11,14	41	...	Do.
75-144		42	126	NE 13	15	...	Do.
75-145		42	126	NW 13	34	...	Do.
75-146		42	126	13,24	25	...	
75-147		42	126	15	60	...	
75-148		42	126	17	26	...	
75-149		42	126	17,18	175	x	
75-150		42	126	18	10	...	
75-151		42	126	19	53	...	
75-152		42	126	19,20	79	...	
75-153		42	126	20,21	20	...	Affected by ditch.
75-154		42	126	21	18	...	Do.
75-155		42	126	21,22	138	x	
75-156		42	126	22,23	63	x	Affected by ditch.
75-157		42	126	23	20	...	Do.
75-158		42	126	23,26	22	...	
75-159		42	126	24	11	...	
75-160		42	126	25,36	84	...	Affected by ditch.
75-161	Harstad Slough..	42	126	29,30	288	x	
75-162		42	126	31	14	...	
75-163		42	126	34	11	...	
26-100					1 (31)	...	See Grant County (26).
75-164	Silver	42	126,127	3:35	76 (133)	x	Also in Grant County (26).
26-101					18 (37)	...	See Grant County (26).
75-165		42,43	124	7:12	52	...	
75-166		42,43	126	30;25	38	x	
26-181					8 (119)	...	See Grant County (26).
76-169	North Drywood..				100 (388)	x	See Swift County (76).
75-167		43	123	NE 3	61	x	Originally meandered with another lake as one lake.
75-168		43	123	NW 3	22	...	Affected by ditch.
75-169		43	123	5-8	230	...	Affected by C.D. 3.
75-170		43	123	10	21	...	Do.
75-171		43	123	12	20	...	Affected by C.D. 30.
75-172		43	123	14,23	21	...	Affected by ditch.
75-173		43	123	16	17	...	
75-174		43	123	17	12	...	
75-175		43	123	20	50	...	Affected by ditch.
75-176		43	123	NE 22	14	...	
75-177		43	123	SE 22	21	...	1951 air photos show part of bed exposed.
75-178		43	123	24,25	15	...	
75-179		43	123	27	15	...	
75-180		43	123	27,34	27	...	

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
75-181		43	123	28	10	...	
75-182		43	123	28,32	13	...	Affected by ditch.
75-183	Drywood	43	123	29,32	74	...	
75-184		43	123	35	22	...	
75-185		43	124	2	34	...	Affected by ditch.
75-186		43	124	2,11	62	x	Affected by C.D. 13.
75-187		43	124	3	17	...	Affected by ditch.
75-188		43	124	3,4	215	...	Affected by C.D. 4.
75-189		43	124	3,10	59	...	Affected by C.D. 13.
75-190		43	124	5	15	...	Affected by C.D. 38.
75-191		43	124	7,18	90	...	Affected by C.D. 18.
75-192	Clear	43	124	8,9,16,17	195	x	
75-193	Mud	43	124	8,17	123	x	Affected by C.D. 18.
75-194		43	124	12	50	...	Affected by ditch.
75-195		43	124	14	28	...	Affected by C.D. 13.
75-196		43	124	15	72	...	Do.
75-197		43	124	18	70	...	Affected by C.D. 18.
75-198		43	124	19	42	...	Do.
75-199	Horseshoe	43	124	19,20	263	x	Do.
75-200	Hattie	43	124	20,21,28,29	488	x	
75-201	Flax	43	124	23-26	136	x	
75-202		43	124	24	27	...	
75-203	Gorder	43	124	25-27,35,36	556	x	
75-204		43	124	28	12	...	Affected by ditch.
75-205		43	124	NC 33	17	...	Do.
75-206		43	124	SC 33	21	...	Do.
75-207		43	124	NE 33	41	...	
75-208		43	124	SE 33	12	...	Affected by ditch.
75-209		43	124	SC 34	78	x	Originally meandered with another lake as one lake.
75-210		43	124,125	5:32,33	40	...	Affected by ditch.
75-211		43	125	CE 1	18	...	Affected by ditch.
75-212		43	125	SW 1	28	...	Do.
75-213		43	125	1,2	32	...	
75-214	Moose	43	125	3,10,11	133	x	Affected by C.D. 1.
75-215		43	125	4	39	...	Do.
75-216		43	125	4,5	42	...	Do.
75-217		43	125	4,9	29	...	
75-218		43	125	5,6	26	...	Affected by ditch.
75-219		43	125	C 7	47	...	Do.
75-220		43	125	NE 7	25	...	Do.
75-221		43	125	8,9	26	...	
75-222		43	125	9	85	...	Affected by C.D. 1.
75-223		43	125	10	35	...	Do.
75-224		43	125	11	11	...	
75-225		43	125	12	26	...	
75-226		43	125	13	13	...	Affected by ditch.
75-227		43	125	14	36	...	Do.
75-228		43	125	15	27	...	
75-229		43	125	17,20	20	...	Affected by C.D. 10.
75-230		43	125	21,22,27,28	187	x	
75-231		43	125	22	23	...	Affected by ditch.
75-232		43	125	22,27	30	...	Do.
75-233		43	125	28,29	38	...	Affected by C.D. 10.
75-234		43	125	29	28	...	Do.
75-235		43	125	29-32	24	...	Do.

Ident. number	Name	Location			Area in Acres	Meandered	Remarks
		Range	Township	Section			
75-236		43	125,126	1:36	34	...	
75-237		43	125,126	2:35	27	...	
75-238	Moose Island	43	125,126	2-4,10,11:34,35	969	x	Affected by C.D. 1
75-239		43	125,126	6:31	92	...	Affected by ditch.
75-240		43	126	1	36	...	
75-241		43	126	2	151	...	
75-242		43	126	C 3	18	...	
75-243		43	126	NC 3	28	...	
75-244		43	126	3,10	104	...	
75-245	Barrett	43	126	C 4	157	x	
75-246		43	126	NE 4	13	...	
75-247		43	126	NC 4	18	...	
75-248		43	126	NW 4	14	...	
75-249		43	126	4,9	40	x	
75-250		43	126	5	32	...	
75-251		43	126	5,8	28	...	
75-252		43	126	6	10	...	
75-253		43	126	7	21	...	
75-254		43	126	9,10	16	...	Affected by ditch.
75-255		43	126	10	23	...	Do.
75-256		43	126	10,15	19	...	Do.
75-257		43	126	11	34	...	
75-258		43	126	14,15	64	...	Affected by C.D. 1.
75-259		43	126	17	32	...	Do.
75-260		43	126	18,19	81	...	Do.
75-261		43	126	20,21	13	...	Do.
75-262		43	126	SC 20,29	32	...	Affected by C.D. 8.
75-263		43	126	SW 20,29	41	...	Do.
75-264		43	126	21,28	100	...	Affected by C.D. 1.
75-265		43	126	22	130	...	Do.
75-266		43	126	22,23	127	...	Do.
75-267		43	126	25	52	...	
75-268		43	126	25,26	91	x	
75-269		43	126	25,36	28	...	Affected by ditch.
75-270		43	126	C 26	31	...	Affected by C.D. 1.
75-271		43	126	NC 26	10	...	Do.
75-272		43	126	28	63	...	Do.
75-273		43	126	28,33	107	...	Affected by ditch.
75-274		43	126	30	16	...	
75-275		43	126	31	11	...	
75-276		43	126	36	58	...	Affected by ditch.
26-185	Cottonwood				69 (247)	x	See Grant County (26).
75-277	Fish	43,44	125	6,7:1,12	267	x	Affected by ditch.
75-278		43,44	126	6:1	42	...	
75-279		43,44	126	18,19:13,24	91	x	Affected by C.D. 7.
75-280		44	123	4,9	27	...	
75-281		44	123	EC 5	13	...	
75-282		44	123	NC 5	37	...	
75-283	Grossman Slough	44	123	5,6	93	x	
75-284		44	123	6	23	...	Affected by ditch.
75-285		44	123	21,28	40	...	Do.
75-286		44	123	31	27	...	
75-287		44	123,124	4:33	104	...	
75-288		44	123,124	6:31	25	...	
75-289	Clark	44	124	4,8,9,16,17	343	x	Affected by C.D. 2.
75-290		44	124	8	13	...	Affected by ditch.
75-291	Gravel	44	124	8,17,18	128	x	
75-292		44	124	13,24	34	...	Affected by C.D. 18.
75-293		44	124	C 15	31	...	Affected by C.D. 2.
75-294		44	124	SW 15	28	...	Do.

DIVISION OF WATERS, SOILS AND MINERALS

Ident. number	Name	Range	Township	Location Section	Area in Acres	Meandered	Remarks
75-295		44	124	24	13	...	Affected by C.D. 18.
75-296		44	124	25,26,35,36	31	...	Do.
75-297		44	124	27,28,33,34	35	...	Affected by C.D. 14.
75-298		44	124	28,33	41	...	Do.
75-299		44	124	30,31	45	...	Affected by C.D. 2.
75-300	Gunderson Slough	44	124	31,32	119	x	Do.
75-301		44	124	34,35	61	...	Affected by C.D. 25.
75-302		44	124	35,36	18	...	Affected by C.D. 18.
75-303		44	126	1	40	...	
75-304		44	126	1,2	99	x	
75-305		44	126	2	18	...	
75-306		44	126	C 13	14	...	Affected by C.D. 7.
75-307		44	126	NC 13	12	...	Do.
75-308		44	126	18,19	10	...	
75-309	Mud	44	126	19	13	...	
75-310		44	126	C 36	103	...	
75-311		44	126	EC 36	11	...	
26-294					34 (74)	...	See Grant County (26).
75-312		44,45	123	18;13	9 (15)	...	Also in Big Stone County (6).
6-24					23 (56)	...	See Big Stone County (6).
75-313		44,45	123	31;36	18 (21)	...	Also in Big Stone County (6).

