




Minnesota Department of Natural Resources

Division of Waters

Le Sueur County (40)

Ordinary High Water Level Report



Data Date: 04/15/2009

	OHWL Elevation	Vertical Datum	Report Date	
Bossuot				LAKE FINDER
40-73 P	1018.8	NGVD 29	May 19, 1980	
<u>Benchmark:</u> Elevation: 1022.43 NGVD 29 Location: Section: 32 Township: 110 Range: 24 W				
60d spike in west side of a power pole on the slope at the west toe and north end of the Rosenthal dike.				

	OHWL Elevation	Vertical Datum	Report Date	
Clear				LAKE FINDER
40-79 P	1009.5	NGVD 29	October 07, 2002	
<u>Benchmark:</u> Elevation: 1013.50 NGVD 29 Location: Section: 10 Township: 111 Range: 24 W				
Found bent 3/8x8" spike 0.5' above ground in the NW root of a 2.5' maple, 90' south of top centerline of boat ramp.				

	OHWL Elevation	Vertical Datum	Report Date	
Dog				LAKE FINDER
40-112 P	1017.6	NGVD 29	April 28, 2008	
<u>Benchmark:</u> Elevation: 1020.59 NGVD 29 Location: Section: 32 Township: 110 Range: 25 W				
Set 60d spike 1.4' above ground in the north side of a power pole, on south side of CR 18 and first pole west of outlet.				
<u>Benchmark:</u> Elevation: 1019.53 NGVD 29 Location: Section: 32 Township: 110 Range: 25 W				
The top left end of upstream headwall of outlet structure.				

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
Eggert 40-29 P	1027.4	NGVD 29	June 14, 2002	LAKE FINDER
<u>Benchmark:</u>	Elevation: 1032.83 NGVD 29	Location:	Section: 32 Township: 112 Range: 23 W	
	Horizontal spike in west side of 30" oak on SW shore of Eggert Lake. 300' N of CoRd, 50' E of NS fence, 200' SE of CoDi #48, 800' NE of vacant school. Found in good condition on 3/11/2000.			
<u>Benchmark:</u>	Elevation: 1032.03 NGVD 29	Location:	Section: 32 Township: 112 Range: 23 W	
	Chiseled square in U.S. Centerline of bridge.			
<u>Benchmark:</u>	Elevation: 1032.04 NGVD 29	Location:	Section: 32 Township: 112 Range: 23 W	
	Top west (upstream) end of concrete arch culvert (10' wide, 6.4' high, 0.75' thick) under township road.			

	OHWL Elevation	Vertical Datum	Report Date	
Elysian 81-95 P	1018.0	NGVD 29	April 22, 1939	LAKE FINDER
<u>Benchmark:</u>	Elevation: 1017.87 NGVD 29	Location:	Section: 28 Township: 108 Range: 24 W	
	Chiseled X in top upstream end right abutment of wildlife outlet structure.			
<u>Benchmark:</u>	Elevation: 1024.37 NGVD 29	Location:	Section: 28 Township: 108 Range: 24 W	
	Found chiseled X in top NE abutment of MHD bridge #3756 1922. (From DNR-BOE dwg #G-373).			
<u>Benchmark:</u>	Elevation: 1020.01 NGVD 29	Location:	Section: 21 Township: 108 Range: 24 W	
	Left upstream abutment over gage at outlet dam.			

	OHWL Elevation	Vertical Datum	Report Date	
Emily 40-124 P	972.6	NGVD 29	May 08, 1987	LAKE FINDER
<u>Benchmark:</u>	Elevation: 975.48 NGVD 29	Location:	Section: 26 Township: 110 Range: 26 W	
	Brass plate in centerline of upstream (north) headwall of outlet bridge			

	OHWL Elevation	Vertical Datum	Report Date	
Fish 40-51 P	1017.5	NGVD 29	October 07, 1975	LAKE FINDER
	(No benchmark data available)			

	OHWL Elevation	Vertical Datum	Report Date	
Frances 40-57 P	1023.5	NGVD 29	May 29, 1984	LAKE FINDER
	(No benchmark data available)			

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
German 40-63 P	1018.5	NGVD 29	June 22, 1990	LAKE FINDER
<u>Benchmark:</u> Elevation: 1014.88 NGVD 29 Location: Section: 5 Township: 109 Range: 24 W				
Gage zero/measure point on permanent staff gage on right downstream abutment of bridge between German and Jefferson Lakes.				

	OHWL Elevation	Vertical Datum	Report Date	
Goose 40-72 P	1022.3	NGVD 29	November 08, 1984	LAKE FINDER
(No benchmark data available)				
(No benchmark data available)				

	OHWL Elevation	Vertical Datum	Report Date	
Gorman 40-32 P	1026.7	NGVD 29	January 23, 1986	LAKE FINDER
<u>Benchmark:</u> Elevation: 1029.35 NGVD 29 Location: Section: 13 Township: 110 Range: 24 W				
On the outlet dam, left end right upstream abutment at S/L slot.				

	OHWL Elevation	Vertical Datum	Report Date	
Hackridge 40-77 P	1005.9	NGVD 29	February 23, 2006	LAKE FINDER
<u>Benchmark:</u> Elevation: 1011.86 NGVD 29 Location: Section: 2 Township: 111 Range: 24 W				
At the outlet, the top south end of the 8' RCP under CoRd 26 (on a faint chiseled and magic marked square).				

	OHWL Elevation	Vertical Datum	Report Date	
Horseshoe 40-1 P	1024.0	NGVD 29	February 01, 2006	LAKE FINDER
<u>Benchmark:</u> Elevation: 1032.19 NGVD 29 Location: Section: 7 Township: 109 Range: 22 W				
At public access, a horizontal 3/8" x 8" spike 1.7' above ground in the north side (directly above a prominent knob) of 2.3' basswood, 16' east from edge of parking area and 44' south of centerline of access road.				

	OHWL Elevation	Vertical Datum	Report Date	
Jefferson 40-92 P	1018.5	NGVD 29	May 26, 1992	LAKE FINDER
<u>Benchmark:</u> Elevation: 1014.88 NGVD 29 Location: Section: 5 Township: 109 Range: 24 W				
Gage zero/measure point on permanent staff gage on right downstream abutment of bridge between German and Jefferson Lakes.				

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
Lily 81-67 P	1024.8	NGVD 29	November 16, 2007	LAKE FINDER
<u>Benchmark:</u>	Elevation: 1032.28 NGVD 29	Location:	Section: 36 Township: 109 Range: 24 W	
At public access, set a horizontal 3/8" x 8" spike 0.5' above ground in the north root of a 1.9' oak, on top of bank 59' E-NE from the top center of the concrete boat ramp and 39' SE from the cl of the road thru the access.				

	OHWL Elevation	Vertical Datum	Report Date	
Mary 40-78 P	1001.1	NGVD 29	September 26, 1980	LAKE FINDER
(No benchmark data available)				

	OHWL Elevation	Vertical Datum	Report Date	
Pepin 40-28 P	1025.0	NGVD 29	June 02, 2001	LAKE FINDER
<u>Benchmark:</u>	Elevation: 1027.27 NGVD 29	Location:	Section: 28 Township: 112 Range: 23 W	
3/8" spk. in the south side of a 1.2' willow, about 5' north of dock at gage readers house.				
<u>Benchmark:</u>	Elevation: 1030.27 NGVD 29	Location:	Section: 33 Township: 112 Range: 23 W	
At PA on N-NW side of lake, vertical 3/8x8" spk in SE root of a 1.9' Ash, 36' E of CL of boat ramp, 7' No of edge of road leading to ramp, on side of steeper bank. 60 d spk 1.5' above grd in SE side of same tree with an elevation of 1030.92.				
<u>Benchmark:</u>	Elevation: 1035.80 NGVD 29	Location:	Section: 34 Township: 112 Range: 23 W	
60d spk in E side of E pole of double power poles at SE corner of Pepin Lk, on west side of Hwy 13. Elev.+1034.89 from 10/6/75 notes, pole has apparently moved.				

	OHWL Elevation	Vertical Datum	Report Date	
Rays 40-56 P	1023.5	NGVD 29	November 16, 1993	LAKE FINDER
(No benchmark data available)				

	OHWL Elevation	Vertical Datum	Report Date	
Rice 40-114 P	146.8	ASSUMED	January 11, 1985	LAKE FINDER
<u>Benchmark:</u>	Elevation: 150.00 ASSUMED	Location:	Section: 15 Township: 111 Range: 25 W	
At outlet of north portion of lake-3/8x8" spike in east side of PP on south side of township road, 2nd pole west of culvert under township road.				
<u>Benchmark:</u>	Elevation: 149.08 ASSUMED	Location:	Section: 15 Township: 111 Range: 25 W	
Found a 60d spike in SE side of a 0.9' ash about 75' right of recent ditching at outlet of south end of south wetland and at edge of cattails. Probably a Bradshaw Survey BM.				

	OHWL Elevation	Vertical Datum	Report Date	
Rice (South portion) 40-114 P	146.8	ASSUMED	January 11, 1985	LAKE FINDER
(No benchmark data available)				

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
Round 40-59 P	1056.2	NGVD 29	October 13, 2003	LAKE FINDER
(No benchmark data available)				
Sabre 40-14 P	1014.1	NGVD 29	March 28, 1977	LAKE FINDER
(No benchmark data available)				
Sanborn 40-27 P	1018.4	NGVD 29	March 15, 2002	LAKE FINDER
<p><u>Benchmark:</u> Elevation: 1018.27 NGVD 29 Location: Section: 26 Township: 112 Range: 23 W</p> <p>At the Sand Creek outlet, the top north end of the 36" CMP thru the field road crossing 670 feet downstream of Sanborn Lake.</p> <p><u>Benchmark:</u> Elevation: 1031.02 NGVD 29 Location: Section: 26 Township: 112 Range: 23 W</p> <p>AT PA on the N side of lake, horizontal slightly bent 3/8x8" spike, 1.1' above grd in E side of a 3.0' oak, on side of bank 57' west of CL of PA entrance road, and 40' N of N edge of parking area.</p>				
Scotch 40-109 P	1011.8	NGVD 29	July 15, 1938	LAKE FINDER
(No benchmark data available)				
Silver 40-106 P	1021.7	NGVD 29	April 10, 2008	LAKE FINDER
<p><u>Benchmark:</u> Elevation: 1024.43 NGVD 29 Location: Section: 11 Township: 110 Range: 25 W</p> <p>Set horizontal 3/8" x 8" spike in W-SW side of a 1.4' ash, 14' south of drive to address #41099 CR 112 and approx. 230' west of outlet culvert under driveway.</p> <p><u>Benchmark:</u> Elevation: 1018.61 NGVD 29 Location: Section: 2 Township: 110 Range: 25 W</p> <p>Top upstream end of a 60" RCP under CR 112 approx. 1900' north of north end of lake at CD 60 crossing.</p>				
Sleepy Eye 40-68 P	144.1	ASSUMED	September 16, 1980	LAKE FINDER
(No benchmark data available)				
Spring 40-123 P	741.5	NGVD 29	February 25, 1974	LAKE FINDER
(No benchmark data available)				

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
Sunfish 40-9 P	1040.1	NGVD 29	December 08, 1986	LAKE FINDER
(No benchmark data available)				
Tetonka 40-31 P	1000.5	NGVD 29	March 09, 2007	LAKE FINDER
<p><u>Benchmark:</u> Elevation: 1004.35 NGVD 29 Location: Section: 27 Township: 109 Range: 23 W</p> <p style="margin-left: 40px;">top centerline bottom step south entrance on E side of house on green indoor/outdoor carpet.</p> <p><u>Benchmark:</u> Elevation: 1007.72 NGVD 29 Location: Section: 27 Township: 109 Range: 23 W</p> <p style="margin-left: 40px;">A magic marker "x" on bolt head at the top upstream end of the right (west) wooden abutment of the Lind Street West bridge over the outlet (Cannon River).</p>				
Thomas 40-95 P	995.2	NGVD 29	November 02, 1994	LAKE FINDER
(No benchmark data available)				
Tustin 40-61 P	1023.4	NGVD 29	May 29, 1984	LAKE FINDER
(No benchmark data available)				
Unnamed 40-138 W	1016.3	NGVD 29	January 28, 1994	LAKE FINDER
<p><u>Benchmark:</u> Elevation: 1020.91 NGVD 29 Location: Section: 4 Township: 111 Range: 24 W</p> <p style="margin-left: 40px;">Slightly bent horizontal 3/8x8" spike in notched east root of a 1.9' oak, on left bank of ditch approximately 100' downstream from beginning of recent ditching.</p> <p><u>Benchmark:</u> Elevation: 1024.31 NGVD 29 Location: Section: 4 Township: 111 Range: 24 W</p> <p style="margin-left: 40px;">Bent 3/8x8" spike, 1.0' above ground, in the east side of a twin (1.8',2.0') oak, 20' west of centerline of C.R. 32 and 50' south of the west end of the outlet culvert under C.R. 32.</p>				
Unnamed 40-99 W	1025.8	NGVD 29	September 10, 1982	LAKE FINDER
(No benchmark data available)				
(No benchmark data available)				
Upper Sakatah 40-2 P	999.2	NGVD 29	June 14, 1960	LAKE FINDER
(No benchmark data available)				

Le Sueur County OHWL Report

	OHWL Elevation	Vertical Datum	Report Date	
Volney				LAKE FINDER
40-33 P	1028.8	NGVD 29	March 26, 1990	

Benchmark: **Elevation:** 1035.79 NGVD 29 **Location:** **Section:** 6 **Township:** 110 **Range:** 23 W

Vertical 3/8x8" spike in S root of 1.4' ash on E slope 50' SSE of the SE corner of conc. boat ramp.

	OHWL Elevation	Vertical Datum	Report Date	
Washington				LAKE FINDER
40-117 P	981.5	NGVD 29	November 08, 1976	

Benchmark: **Elevation:** 987.42 NGVD 29 **Location:** **Section:** 12 **Township:** 109 **Range:** 26 W

Set vertical 3/8" x 8" spike in notched SE root of a twin 2.0' oak. Spk is in remaining trunk (other trunk has been cut off). Tree is on right bank 56' downstream from carp barrier at the outlet.

Benchmark: **Elevation:** 991.60 NGVD 29 **Location:** **Section:** 7 **Township:** 109 **Range:** 25 W

Double bent spike in west base of a 1.6' oak at gage site.

Benchmark: **Elevation:** 989.18 NGVD 29 **Location:** **Section:** 18 **Township:** 109 **Range:** 25 W

At Westwood Marina/public access, the highest point on S-SE top of large painted grey boulder, 4.3' high, at easterly side of parking area, 20' from water's edge.

	OHWL Elevation	Vertical Datum	Report Date	
West Jefferson				LAKE FINDER
40-92 P	1018.5	NGVD 29	May 26, 1992	

(No benchmark data available)