



- ① PARKING LOT IMPROVEMENTS
- ② VAULT TOILET
- ③ PAY BOX/ WAYFINDING
- ④ TRASH/RECYCLING
- ⑤ STONE WALL
- ⑥ INTERPRETIVE CENTER FOOTPRINT
- ⑦ INTERPRETIVE SIGN
- ⑧ EXISTING SMALL POND
- ⑨ SHELTER/EVENT (~36-60 PEOPLE)
- ⑩ BIKE RACKS
- ⑪ SIOUX QUARTZITE BLUFF

Pros

- Minimal amount of disturbance to natural resources of habitat; disturbance is limited to turf areas
- Accessible picnic shelter
- Minimal impact on landscape

Cons

- Majority of Interpretive Center structure removed due to structural deficiencies

In this concept, the trailhead improvements and the disposition of the Interpretive Center remain the same as shown in Concept 01. A new picnic shelter has been added to the southwest of the building footprint. The shelter is oriented to highlight the views to the south and take advantage of the protection offered by the Sioux quartzite bluff directly to the north.



**B PERSPECTIVE B**