

Figure 3. Lower Mound Lake Basin Restoration, Preliminary Design for Proposed Project.





Figure 4. Rock County Flood Hazard Boundary Map







Figure 5. Lower Mound Lake Basin Restoration - NRCS Soil Units in Project Area



*Data Source: MN DNR; U.S. Department of Agriculture, Natural Resources Conservation Service, 2013. This data does not accurately represent current conditions affected by flood events from 2014. Figure updates 2/8/2018.







Figure 6: Lower Mound Lake Basin Restoration - NWI Circ. 39, Class 2009-2014



*NWI Data Source: MN DNR, 2015. Southern Minnesota data based on collected data from 2011. This data does not accurately represent current conditions affected by the flood events from 2014. Figure updated 2/8/2018.





*Data Source: MN DNR, 2014. This data does not accurately represent current conditions affected by the flood events from 2014. Figure updated: 2/8/2018.